SREDKEY2 Cert failed and firmware update

Step 1: **Connect the SREDKEY2 which shows "Cert Failed" to the PC**

Step 2: **Unzip this file and execute**



Cert_Update_Utility	9/2/2022 12:49 PM
Cert_Update_Utility.exe.config	9/2/2022 12:08 PM
Cert_Update_Utility.pdb	9/2/2022 12:49 PM
FW_PROD_SREDKEY2_1.02.003.0472	9/2/2022 12:28 PM
IDTechSDK.dll	9/2/2022 11:54 AM
IDTechSDK.pdb	9/2/2022 11:54 AM
Newtonsoft.Json.dll	3/17/2021 1:03 PM
NLog.dll	12/5/2021 3:42 PM
SREDKey2_HID	9/2/2022 12:30 PM
SREDKey2_KB	9/6/2022 1:16 PM

You should see this, please wait for 5-6 minutes.



Step 3: **You will see the update completely message at the end.**

Certificate Update Utility

```
SREDKey2:028R018885  Main Firmware: Sent block 699 of 721
SREDKey2:028R018885  Main Firmware: Sent block 700 of 721
SREDKey2:028R018885  Main Firmware: Sent block 701 of 721
SREDKey2:028R018885  Main Firmware: Sent block 702 of 721
SREDKey2:028R018885  Main Firmware: Sent block 703 of 721
SREDKey2:028R018885  Main Firmware: Sent block 704 of 721
SREDKey2:028R018885  Main Firmware: Sent block 705 of 721
SREDKey2:028R018885  Main Firmware: Sent block 706 of 721
SREDKey2:028R018885  Main Firmware: Sent block 707 of 721
SREDKey2:028R018885  Main Firmware: Sent block 708 of 721
SREDKey2:028R018885  Main Firmware: Sent block 709 of 721
SREDKey2:028R018885  Main Firmware: Sent block 710 of 721
SREDKey2:028R018885  Main Firmware: Sent block 711 of 721
SREDKey2:028R018885  Main Firmware: Sent block 712 of 721
SREDKey2:028R018885  Main Firmware: Sent block 713 of 721
SREDKey2:028R018885  Main Firmware: Sent block 714 of 721
SREDKey2:028R018885  Main Firmware: Sent block 715 of 721
SREDKey2:028R018885  Main Firmware: Sent block 716 of 721
SREDKey2:028R018885  Main Firmware: Sent block 717 of 721
SREDKey2:028R018885  Main Firmware: Sent block 718 of 721
SREDKey2:028R018885  Main Firmware: Sent block 719 of 721
SREDKey2:028R018885  Main Firmware: Sent block 720 of 721
SREDKey2:028R018885  Main Firmware: Sent block 721 of 721
SREDKey2:028R018885  Applying Firmware Update....
SREDKey2:028R018885  Firmware Update Successful
SREDKey2:028R018885  K81 Loaded Successfully. v1.02.003.0472.S
SREDKey2:028R018885  SREDKey2 Firmware Update Completed Successfully.
SREDKey2:028R018885  Update From Archive Completed Successfully
```