


6800 Cert failed and firmware update

Step 1: Connect the 6800 which shows “Cert Failed” to the PC

Step 2: Unzip this file and execute



You should see this, please wait for 5-6 minutes.

```
Certificate Update Utility
***** IDTech Certificate Update Utility *****

This utility will auto-update certs when a supported device is connected.

VP3600:129T764857 Updating Certificates Attempt #1
VP3600:129T764857 Certificates Successfully Updated
VP3600:129T764857 Preparing for firmware update...
```

 Certificate Update Utility

***** IDTech Certificate Update Utility *****

This utility will auto-update certs when a supported device is connected.

```
VP3600:129T764857 Updating Certificates Attempt #1
VP3600:129T764857 Certificates Successfully Updated
VP3600:129T764857 Preparing for firmware update...
VP3600:129T764857 <FW_SUCCESS> Firmware Update Successful
VP3600:129T764857 All operations completed
VP3600:129T764857 Update From Archive Started...
VP3600:129T764857 Main Firmware: Sent block 2 of 1210
VP3600:129T764857 Main Firmware: Sent block 1 of 1210
VP3600:129T764857 Starting VP3600 Firmware Update...
VP3600:129T764857 Starting Bootloader A Update Process...
VP3600:129T764857 Bootloader A Update Not Required. v1.15
VP3600:129T764857 Entering Bootloader Mode....
VP3600:129T764857 Starting K81 Update Process...
VP3600:129T764857 Main Firmware: Sent block 3 of 1210
VP3600:129T764857 Main Firmware: Sent block 4 of 1210
VP3600:129T764857 Main Firmware: Sent block 5 of 1210
VP3600:129T764857 Main Firmware: Sent block 6 of 1210
VP3600:129T764857 Main Firmware: Sent block 7 of 1210
VP3600:129T764857 Main Firmware: Sent block 8 of 1210
VP3600:129T764857 Main Firmware: Sent block 9 of 1210
VP3600:129T764857 Main Firmware: Sent block 10 of 1210
VP3600:129T764857 Main Firmware: Sent block 11 of 1210
VP3600:129T764857 Main Firmware: Sent block 12 of 1210
VP3600:129T764857 Main Firmware: Sent block 13 of 1210
VP3600:129T764857 Main Firmware: Sent block 14 of 1210
VP3600:129T764857 Main Firmware: Sent block 15 of 1210
VP3600:129T764857 Main Firmware: Sent block 16 of 1210
VP3600:129T764857 Main Firmware: Sent block 17 of 1210
VP3600:129T764857 Main Firmware: Sent block 18 of 1210
VP3600:129T764857 Main Firmware: Sent block 19 of 1210
VP3600:129T764857 Main Firmware: Sent block 20 of 1210
VP3600:129T764857 Main Firmware: Sent block 21 of 1210
VP3600:129T764857 Main Firmware: Sent block 22 of 1210
VP3600:129T764857 Main Firmware: Sent block 23 of 1210
VP3600:129T764857 Main Firmware: Sent block 24 of 1210
VP3600:129T764857 Main Firmware: Sent block 25 of 1210
VP3600:129T764857 Main Firmware: Sent block 26 of 1210
VP3600:129T764857 Main Firmware: Sent block 27 of 1210
VP3600:129T764857 Main Firmware: Sent block 28 of 1210
VP3600:129T764857 Main Firmware: Sent block 29 of 1210
VP3600:129T764857 Main Firmware: Sent block 30 of 1210
VP3600:129T764857 Main Firmware: Sent block 31 of 1210
VP3600:129T764857 Main Firmware: Sent block 32 of 1210
VP3600:129T764857 Main Firmware: Sent block 33 of 1210
VP3600:129T764857 Main Firmware: Sent block 34 of 1210
VP3600:129T764857 Main Firmware: Sent block 35 of 1210
VP3600:129T764857 Main Firmware: Sent block 36 of 1210
VP3600:129T764857 Main Firmware: Sent block 37 of 1210
VP3600:129T764857 Main Firmware: Sent block 38 of 1210
VP3600:129T764857 Main Firmware: Sent block 39 of 1210
VP3600:129T764857 Main Firmware: Sent block 40 of 1210
VP3600:129T764857 Main Firmware: Sent block 41 of 1210
VP3600:129T764857 Main Firmware: Sent block 42 of 1210
VP3600:129T764857 Main Firmware: Sent block 43 of 1210
VP3600:129T764857 Main Firmware: Sent block 44 of 1210
VP3600:129T764857 Main Firmware: Sent block 45 of 1210
```

Step 3: You will see the update completely message at the end.

```

Certificate Update Utility
VP3600:129T764857 Main Firmware: Sent block 1157 of 1210
VP3600:129T764857 Main Firmware: Sent block 1158 of 1210
VP3600:129T764857 Main Firmware: Sent block 1159 of 1210
VP3600:129T764857 Main Firmware: Sent block 1160 of 1210
VP3600:129T764857 Main Firmware: Sent block 1161 of 1210
VP3600:129T764857 Main Firmware: Sent block 1162 of 1210
VP3600:129T764857 Main Firmware: Sent block 1163 of 1210
VP3600:129T764857 Main Firmware: Sent block 1164 of 1210
VP3600:129T764857 Main Firmware: Sent block 1165 of 1210
VP3600:129T764857 Main Firmware: Sent block 1166 of 1210
VP3600:129T764857 Main Firmware: Sent block 1167 of 1210
VP3600:129T764857 Main Firmware: Sent block 1168 of 1210
VP3600:129T764857 Main Firmware: Sent block 1169 of 1210
VP3600:129T764857 Main Firmware: Sent block 1170 of 1210
VP3600:129T764857 Main Firmware: Sent block 1171 of 1210
VP3600:129T764857 Main Firmware: Sent block 1172 of 1210
VP3600:129T764857 Main Firmware: Sent block 1173 of 1210
VP3600:129T764857 Main Firmware: Sent block 1174 of 1210
VP3600:129T764857 Main Firmware: Sent block 1175 of 1210
VP3600:129T764857 Main Firmware: Sent block 1176 of 1210
VP3600:129T764857 Main Firmware: Sent block 1177 of 1210
VP3600:129T764857 Main Firmware: Sent block 1178 of 1210
VP3600:129T764857 Main Firmware: Sent block 1179 of 1210
VP3600:129T764857 Main Firmware: Sent block 1180 of 1210
VP3600:129T764857 Main Firmware: Sent block 1181 of 1210
VP3600:129T764857 Main Firmware: Sent block 1182 of 1210
VP3600:129T764857 Main Firmware: Sent block 1183 of 1210
VP3600:129T764857 Main Firmware: Sent block 1184 of 1210
VP3600:129T764857 Main Firmware: Sent block 1185 of 1210
VP3600:129T764857 Main Firmware: Sent block 1186 of 1210
VP3600:129T764857 Main Firmware: Sent block 1187 of 1210
VP3600:129T764857 Main Firmware: Sent block 1188 of 1210
VP3600:129T764857 Main Firmware: Sent block 1189 of 1210
VP3600:129T764857 Main Firmware: Sent block 1190 of 1210
VP3600:129T764857 Main Firmware: Sent block 1191 of 1210
VP3600:129T764857 Main Firmware: Sent block 1192 of 1210
VP3600:129T764857 Main Firmware: Sent block 1193 of 1210
VP3600:129T764857 Main Firmware: Sent block 1194 of 1210
VP3600:129T764857 Main Firmware: Sent block 1195 of 1210
VP3600:129T764857 Main Firmware: Sent block 1196 of 1210
VP3600:129T764857 Main Firmware: Sent block 1197 of 1210
VP3600:129T764857 Main Firmware: Sent block 1198 of 1210
VP3600:129T764857 Main Firmware: Sent block 1199 of 1210
VP3600:129T764857 Main Firmware: Sent block 1200 of 1210
VP3600:129T764857 Main Firmware: Sent block 1201 of 1210
VP3600:129T764857 Main Firmware: Sent block 1202 of 1210
VP3600:129T764857 Main Firmware: Sent block 1203 of 1210
VP3600:129T764857 Main Firmware: Sent block 1204 of 1210
VP3600:129T764857 Main Firmware: Sent block 1205 of 1210
VP3600:129T764857 Main Firmware: Sent block 1206 of 1210
VP3600:129T764857 Main Firmware: Sent block 1207 of 1210
VP3600:129T764857 Main Firmware: Sent block 1208 of 1210
VP3600:129T764857 Main Firmware: Sent block 1209 of 1210
VP3600:129T764857 Main Firmware: Sent block 1210 of 1210
VP3600:129T764857 Applying Firmware Update...
VP3600:129T764857 Firmware Update Successful
VP3600:129T764857 K81 Loaded Successfully. v1.03.019.0428
VP3600:129T764857 VP3600 Firmware Update Completed Successfully.
VP3600:129T764857 Update From Archive Completed Successfully
```